Automotive TechTips



Volume 3 • Issue 2

Maximizing bearing performance and life remains an objective throughout The Timken Company, from design teams and manufacturing associates to our field sales team and distributors. Tech Tips help you install and maintain Timken® bearings, seals and components to maximize their life and performance and the systems in which they operate. For more information regarding Timken automotive products and services, visit www.timken.com or contact your local Timken distributor.

TAPERED ROLLER BEARING DAMAGE ANALYSIS



The most common types of bearing damage that may result in a reduction of bearing or application life are often caused by:

insufficient maintenance practices

mishandling

improper installation and adjustment practices

inadequate lubrication

The following offers a quick reference to the common causes of bearing damage.

FATIGUE SPALLING



Geometric stress concentration:

Spalling from misalignment, deflections or heavy loading.



Inclusion origin: Spalling from

oxides or other hard inclusions in bearing steel.



Point surface origin:

Spalling

from debris or raised metal exceeding the lubricant film thickness.

FOREIGN MATERIAL



wear: Fine abrasive particle contamination.

Abrasive



Debris from other fatigued parts, inad-

equate sealing or poor maintenance.



Grooving: Large particle

contamination embedding into soft cage material.

INADEQUATE LUBRICATION*



Roller end scoring: Metal-to-

metal contact from breakdown of lubricant film.



Cone large rib

face scoring: 'Welding' and heat damage from metal-to-metal contact.



Cone large rib face deformation:

Metal flow from excessive heat generation.



Total bear-

ing lock-up:

Rollers skew, slide sideways and lock-up bearing.

* Excessive preload can cause damage similar to inadequate lubrication damage.

CORROSION/ **ETCHING**



Staining: Surface stain with

no significant corrosion from moisture exposure.



Etching: Rusting

with pitting and corrosion from moisture/water exposure.



Line spalling: Roller spaced

spalling from bearings operating after etching damage.

FALSE BRINELLING



Wear caused by vibration or relative axial movement between rollers and races.

HANDLING DAMAGE

Roller spaced nicking:

Raised metal on races from contact with roller edges.



handling or installation damage.



Cup-face denting: Indentations from hardened driver.

CAGE DAMAGE



erly installed or dropped bearing.



Cage ring compressed during installation or interference during service.



Irregular roller path from deflection, inaccurate machining or wear of bearing seats.

PEELING

Micro-spalling due to thin lubricant film from high loads/low RPM or elevated temperatures.

HIGH SPOTS IN CUP SEATS



Localized spalling on the cup race from stress riser created by split housing pinch point.

IMPROPER FIT



cone due to out-of-round or oversized shaft.

> Cup spinning: Loose

cup fit in a rotating wheel hub.

EXCESSIVE PRELOAD OR OVERLOAD



Rapid and deep spalling caused by unusually high stresses. Full race width fatigue spalling is caused by heavy loads creating

MARNING Failure to observe the following warnings could create a risk of serious bodily harm.

Proper maintenance and handling practices are critical. Failure to follow installation instructions and to maintain proper lubrication can result in equipment failure.

Never spin a bearing with compressed air. The rolling elements may be forcefully expelled.

TechTips is not intended to substitute for the specific recommendations of your equipment suppliers.

a thin lubricant film and elevated temperatures.

TRUE BRINELLING



Damage from shock or impact.

ELECTRIC CURRENT



Electric arc pitting: Small burns created by arcs from improper electric grounding while the bearing is stationary.



Fluting: Series of small axial burns caused by electric current passing through the bearing while it is rotating.

EXCESSIVE END PLAY



Scalloping: Uneven localized

wear resulting from excessive end play.



Cage pocket wear: Heavy con-

tact between the rollers and cage pocket surfaces caused by bearing operating too loosely.



www.timken.com

Timken® is a registered trademark of The Timken Company

© 2008 The Timken Company Printed in U.S.A. 10M 01-08-29 Order No.7582

MISALIGNMENT



